



US EPA RECORDS CENTER REGION 5
 461048

EGAN MARINE CORPORATION
 T05-9410-153 DIR: DOWN
 10/20/94 TIME: 1030
 PHOTOGRAPHER: KRIEG
 DESC: VIEW OF THE WATER AND
 THE DRAINAGE OUTFALL.



EGAN MARINE CORPORATION
 T05-9410-153 DIR:
 10/20/94 TIME: 1029
 PHOTOGRAPHER: KRIEG
 DESC: DRAINAGE OUTFALL PORT
 ON THE BARGE SLIP.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: N
 10/20/94 TIME: 1031
 PHOTOGRAPHER: KRIEG
 DESC: NEWLY INSTALLED
 OIL/WATER SEPARATOR.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1035
 PHOTOGRAPHER: KRIEG
 DESC: VIEW OF THE 25K GLASS
 LINED TANKS.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: N
 10/20/94 TIME: 1035
 PHOTOGRAPHER: KRIEG
 DESC: VIEW OF THE OIL WATER
 SEPARATOR.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1035
 PHOTOGRAPHER: KRIEG
 DESC: VIEW OF THE SHALLOW
 PIT.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: W
 10/20/94 TIME: 1037
 PHOTOGRAPHER: KRIEG
 DESC: BACK SIDE OF 25K GLASS
 LINED TANKS BY ROAD.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: N
 10/20/94 TIME: 1037
 PHOTOGRAPHER: KRIEG
 DESC: DIESEL FUEL STORAGE
 TANKS USED FOR TRUCKS.




EGAN MARINE CORPORATION
 T05-9410-153 DIR: SW
 10/20/94 TIME: 1039
 PHOTOGRAPHER: KRIEG
 DESC: POLY TANKS NEXT TO THE
 27K VERTICAL TANKS.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: W
 10/20/94 TIME: 1041
 PHOTOGRAPHER: KRIEG
 DESC: HOMOGENIZED VEG. OIL
 DRUMS ON WESTERN PEN.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: W
 10/20/94 TIME: 1041
 PHOTOGRAPHER: KRIEG
 DESC: HOMOGENIZED VEG. OIL
 DRUM LABELS.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1203
 PHOTOGRAPHER: TREBILC
 DESC: OIL STAIN LINE, ROCK
 SLOPE OF THE BARGE



EGAN MARINE CORPORATION
 T05-9410-153 DIR: W
 10/20/94 TIME: 1204
 PHOTOGRAPHER: TREBILC
 DESC: DRAINAGE OUTFALL PORT
 INTO THE BARGE SLIP.




EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1205
 PHOTOGRAPHER: TREBILC
 DESC: STAINS ON THE ROCK
 SLOPE BY THE BARGE



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1205
 PHOTOGRAPHER: TREBILC
 DESC: STAINS ON THE ROCK
 SLOPE BY THE BARGE



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1205
 PHOTOGRAPHER: TREBILC
 DESC: DRAINAGE OUTFALL PORT
 AND STAINS ON ROCKS.



EGAN MARINE CORPORATION
T05-9410-153 DIR: W
10/20/94 TIME: 1205
PHOTOGRAPHER: TREBILC
DESC: SEEPAGE FROM THE ROCK
SLOPE INTO THE SLIP.



EGAN MARINE CORPORATION
T05-9410-153 DIR: SW
10/20/94 TIME: 1208
PHOTOGRAPHER: KRIEG
DESC: STAINED SOIL BY THE
MAINT. BLDG., WEST PEN.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1215
 PHOTOGRAPHER: KRIEG
 DESC: NEWLY GRAVELED AREA
 COVERING OIL SOAKED



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1215
 PHOTOGRAPHER: KRIEG
 DESC: OILY SHEEN IN PUDDLE
 BY NEWLY GRAVELED AREA.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: W
 10/20/94 TIME: 1223
 PHOTOGRAPHER: KRIEG
 DESC: HOMOGENIZED VEG. OIL
 DRUM LABELS.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: S
 10/20/94 TIME: 1223
 PHOTOGRAPHER: KRIEG
 DESC: WATER PUDDLE WITH OILY
 SHEEN ON WESTERN PEN.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: SW
 10/20/94 TIME: 1224
 PHOTOGRAPHER: KRIEG
 DESC: WATER PUDDLE WITH OILY
 SHEEN ON WESTERN PEN.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: N
 10/20/94 TIME: 1225
 PHOTOGRAPHER: KRIEG
 DESC: VIEW OF 27K VERTICAL
 TANKS ON WESTERN PEN.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: SW
 10/20/94 TIME: 1226
 PHOTOGRAPHER: KRIEG
 DESC: WATER PUDDLE WITH OILY
 SHEEN ON WESTERN PEN.




EGAN MARINE CORPORATION
 T05-9410-153 DIR: W
 10/20/94 TIME: 1226
 PHOTOGRAPHER: KRIEG
 DESC: HOMOGENIZED VEG. OIL
 DRUM LABELS.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: W
 10/20/94 TIME: 1227
 PHOTOGRAPHER: KRIEG
 DESC: GREEN STAINED SOIL
 NEAR HOMO. VEG. OIL



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1227
 PHOTOGRAPHER: KRIEG
 DESC: WATER PUDDLE WITH OILY
 SHEEN, WEST OF 27K



EGAN MARINE CORPORATION
 T05-9410-153 DIR: SW
 10/20/94 TIME: 1227
 PHOTOGRAPHER: KRIEG
 DESC: WATER PUDDLE WITH OILY
 SHEEN, WEST OF 27K



EGAN MARINE CORPORATION
 T05-9410-153 DIR: E
 10/20/94 TIME: 1228
 PHOTOGRAPHER: KRIEG
 DESC: OIL SATURATED SOIL
 UNDER THE WHITE ROCK.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: SW
 10/20/94 TIME: 1230
 PHOTOGRAPHER: KRIEG
 DESC: 5 GAL. PAILS FILLED
 WITH OIL BY 27K TANKS.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NE
 10/20/94 TIME: 1235
 PHOTOGRAPHER: KRIEG
 DESC: DIESEL/ASPHALT/OIL
 TANKS BY MAINT. BLDG.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: W
 10/20/94 TIME: 1251
 PHOTOGRAPHER: KRIEG
 DESC: OIL PUDDLE BEHIND DUMP
 TRUCK, EASTERN PEN.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NE
 10/20/94 TIME: 1253
 PHOTOGRAPHER: KRIEG
 DESC: 8K GAL. TANK WITH
 STAIN, EASTERN PEN.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1253
 PHOTOGRAPHER: KRIEG
 DESC: OPEN 55 GAL. DRUMS
 FILLED WITH OILY WASTE.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: W
 10/20/94 TIME: 1423
 PHOTOGRAPHER: KRIEG
 DESC: EGAN CREW MOVING DRUMS
 WITH OILY WASTES.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: S
 10/20/94 TIME: 1422
 PHOTOGRAPHER: KRIEG
 DESC: EGAN CREW MOVING OIL
 SATURATED SOIL PILE.




EGAN MARINE CORPORATION
 T05-9410-153 DIR: SE
 10/20/94 TIME: 1422
 PHOTOGRAPHER: KRIEG
 DESC: EGAN CREW MOVING OIL
 SATURATED SOIL PILE.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: W
 10/20/94 TIME: 1423
 PHOTOGRAPHER: KRIEG
 DESC: EGAN CREW MOVING DRUMS
 WITH OILY WASTES.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: S
 10/20/94 TIME: 1423
 PHOTOGRAPHER: KRIEG
 DESC: VIEW OF LARGE STORAGE
 TANKS ON EASTERN PEN.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: SW
 10/20/94 TIME: 1423
 PHOTOGRAPHER: KRIEG
 DESC: 15K TANK WITH LEAK
 STAINS ON TANK AND



EGAN MARINE CORPORATION
 T05-9410-153 DIR: N
 10/20/94 TIME: 1424
 PHOTOGRAPHER: KRIEG
 DESC: 55 GAL DRUM WITH OIL
 NEXT TO BARGE SLIP.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NE
 10/20/94 TIME: 1425
 PHOTOGRAPHER: KRIEG
 DESC: OIL STAINED SOIL
 BEHIND DUMP TRUCK.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: N
 10/20/94 TIME: 1425
 PHOTOGRAPHER: KRIEG
 DESC: OIL STAINED SOIL UNDER
 PUMP BY THE BARGE SLIP.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1425
 PHOTOGRAPHER: KRIEG
 DESC: OIL STAINED SOIL UNDER
 PUMP BY BARGE SLIP.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1426
 PHOTOGRAPHER: KRIEG
 DESC: OIL STAINED SOIL BY
 PUMP AND DUMP TRUCK.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: SW
 10/20/94 TIME: 1428
 PHOTOGRAPHER: KRIEG
 DESC: STAINED SOIL AND ROCK
 ON THE EASTERN



EGAN MARINE CORPORATION
 T05-9410-153 DIR: S
 10/20/94 TIME: 1428
 PHOTOGRAPHER: KRIEG
 DESC: STAINED SOIL AND ROCK
 ON THE EASTERN



EGAN MARINE CORPORATION
 T05-9410-153 DIR: SW
 10/20/94 TIME: 1428
 PHOTOGRAPHER: KRIEG
 DESC: STAINED SOIL AND ROCK
 ON THE EASTERN



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NE
 10/20/94 TIME: 1429
 PHOTOGRAPHER: KRIEG
 DESC: VIEW OF THE LARGE
 STORAGE TANKS, EAST



EGAN MARINE CORPORATION
 T05-9410-153 DIR: S
 10/20/94 TIME: 1429
 PHOTOGRAPHER: KRIEG
 DESC: STAINED SOIL AND ROCK
 ON THE EASTERN



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NE
 10/20/94 TIME: 1430
 PHOTOGRAPHER: KRIEG
 DESC: OPEN 55 GAL WASTE OIL
 DRUMS ON THE EAST PEN.



EGAN MARINE CORPORATION
T05-9410-153 DIR: N
10/20/94 TIME: 1430
PHOTOGRAPHER: KRIEG
DESC: OPEN 55 GAL WASTE OIL
DRUMS ON THE EAST PEN.



EGAN MARINE CORPORATION
T05-9410-153 DIR: N
10/20/94 TIME: 1431
PHOTOGRAPHER: KRIEG
DESC: OPEN WASTE OIL DRUMS
AND STACKED OIL DRUMS.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NE
 10/20/94 TIME: 1431
 PHOTOGRAPHER: KRIEG
 DESC: OPEN 55 GAL WASTE OIL
 DRUMS ON EASTERN PEN.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1432
 PHOTOGRAPHER: KRIEG
 DESC: OPEN WASTE OIL DRUMS
 AND STACKED OIL DRUMS.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: NW
 10/20/94 TIME: 1433
 PHOTOGRAPHER: KRIEG
 DESC: STACKED OIL DRUMS
 BEHIND STORAGE BLDG.



EGAN MARINE CORPORATION
 T05-9410-153 DIR: SW
 10/20/94 TIME: 1434
 PHOTOGRAPHER: KRIEG
 DESC: LEAKING DRUM IN THE
 STACKED OIL DRUMS.



EGAN MARINE CORPORATION
T05-9410-153 DIR: S
10/20/94 TIME: 1436
PHOTOGRAPHER: KRIEG
DESC: VIEW OF THE LARGE
STORAGE TANKS, EAST



EGAN MARINE CORPORATION
T05-9410-153 DIR: E
10/20/94 TIME: 1438
PHOTOGRAPHER: CARR
DESC: FRONT GATE TO EGAN
MARINE CORPORATION.



EGAN MARINE CORPORATION
T05-9410-153 DIR: 360°
10/20/94 TIME: 1025
PHOTOGRAPHER: KRIEG
DESC: PAN SHOT OF FACILITY
FROM THE DRAINAGE PORT.




EGAN MARINE CORPORATION
T05-9410-153 DIR: 360°
10/20/94 TIME: 1025
PHOTOGRAPHER: KRIEG
DESC: PAN SHOT OF FACILITY
FROM THE DRAINAGE PORT.




EGAN MARINE CORPORATION
T05-9410-153 DIR: 360°
10/20/94 TIME: 1025
PHOTOGRAPHER: KRIEG
DESC: PAN SHOT OF FACILITY
FROM THE DRAINAGE PORT.



EGAN MARINE CORPORATION
T05-9410-153 DIR: E
10/20/94 TIME: 1038
PHOTOGRAPHER: KRIEG
DESC: PAN SHOT OF VEG. OIL
STORAGE TANKS, WEST



EGAN MARINE CORPORATION
T05-9410-153 DIR: E
10/20/94 TIME: 1038
PHOTOGRAPHER: KRIEG
DESC: PAN SHOT OF VEG. OIL
STORAGE TANKS, WEST



EGAN MARINE CORPORATION
T05-9410-153 DIR: W
10/20/94 TIME: 1035
PHOTOGRAPHER: KRIEG
DESC: PAN SHOT OF THE 25K
TANKS IN THE SHALLOW

